

割出表

T : 分割数

H : 使用する割出板 (No.51) と穴数

N : クランクハンドル (No.54) の回転数と整数回転数に追加する穴数

| T | H | N | T | H | N | T | H | N |
|----|------|----------|----|------|---------|-----|------|--------|
| 1 | | | 35 | B-21 | 2 12/21 | 69 | B-23 | 1 7/23 |
| 2 | | 45 | 36 | A-20 | 2 10/20 | 70 | B-21 | 1 6/21 |
| 3 | | 30 | 37 | C-37 | 2 16/37 | 71 | | |
| 4 | A-20 | 22 10/20 | 38 | A-19 | 2 7/19 | 72 | A-20 | 1 5/20 |
| 5 | | 18 | 39 | C-39 | 2 12/39 | 73 | | |
| 6 | | 15 | 40 | A-20 | 2 5/20 | 74 | C-37 | 1 8/37 |
| 7 | B-21 | 12 18/21 | 41 | C-41 | 2 8/41 | 75 | A-20 | 1 4/20 |
| 8 | A-20 | 11 5/20 | 42 | B-21 | 2 3/21 | 76 | | |
| 9 | | 10 | 43 | C-43 | 2 4/43 | 77 | | |
| 10 | | 9 | 44 | | | 78 | C-39 | 1 6/39 |
| 11 | B-33 | 8 6/33 | 45 | | 2 | 79 | | |
| 12 | A-20 | 7 10/20 | 46 | B-23 | 1 22/23 | 80 | A-16 | 1 2/16 |
| 13 | C-39 | 6 36/39 | 47 | C-47 | 1 43/47 | 81 | A-18 | 1 2/18 |
| 14 | B-21 | 6 9/21 | 48 | A-16 | 1 14/16 | 82 | C-41 | 1 4/41 |
| 15 | | 6 | 49 | C-49 | 1 41/49 | 83 | | |
| 16 | A-16 | 5 10/16 | 50 | A-20 | 1 16/20 | 84 | | |
| 17 | A-17 | 5 5/17 | 51 | A-17 | 1 13/17 | 85 | A-17 | 1 1/17 |
| 18 | | 5 | 52 | | | 86 | C-43 | 1 2/43 |
| 19 | A-19 | 4 14/19 | 53 | | | 87 | B-29 | 1 1/29 |
| 20 | A-20 | 4 10/20 | 54 | A-18 | 1 12/18 | 88 | | |
| 21 | B-21 | 4 6/21 | 55 | B-33 | 1 21/33 | 89 | | |
| 22 | B-33 | 4 3/33 | 56 | | | 90 | | 1 |
| 23 | B-23 | 3 21/23 | 57 | A-19 | 1 11/19 | 91 | | |
| 24 | A-20 | 3 15/20 | 58 | B-29 | 1 16/29 | 92 | | |
| 25 | A-20 | 3 12/20 | 59 | | | 93 | B-31 | 30/31 |
| 26 | C-39 | 3 18/39 | 60 | A-20 | 1 10/20 | 94 | C-47 | 45/47 |
| 27 | A-18 | 3 6/18 | 61 | | | 95 | A-19 | 18/19 |
| 28 | | | 62 | B-31 | 1 14/31 | 96 | A-16 | 15/16 |
| 29 | B-29 | 3 3/29 | 63 | B-21 | 1 9/21 | 97 | | |
| 30 | | 3 | 64 | | | 98 | C-49 | 45/49 |
| 31 | B-31 | 2 28/31 | 65 | C-39 | 1 15/39 | 99 | B-33 | 30/33 |
| 32 | A-16 | 2 13/16 | 66 | B-33 | 1 12/33 | 100 | A-20 | 18/20 |
| 33 | B-33 | 2 24/33 | 67 | | | | | |
| 34 | A-17 | 2 11/17 | 68 | | | | | |